

# Oil Field Environmental Incident Summary

**Incident:** 20151124132819

**Date/Time of Notice:** 11/24/2015 13:28

**Responsible Party:** Enable Midstream

**Well Operator:** BUCKHORN ENERGY SERVICES, LLC

**Well Name:** LARMER 6-6

**Field Name:** HOFFLUND

**Well File #:** 8981

**Date Incident:** 11/24/2015

**Time Incident:** 08:00

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 154

**Rng:** 95

**Sec:** 6

**Qtr:** SE NW

**Location Description:**

**Submitted By:** Nancy Roberts

**Received By:**

**Contact Person:** David Parker

5613 DTC PARKWAY SUITE 800

GREENWOOD VILLAGE, CO 80111-3036

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Other

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	200	Barrels				

**Description of Other Released Contaminant:**

Fresh water

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

none

**Areal Extent:**

***Potential Environmental Impacts:***

none

***Action Taken or Planned:***

Enable is currently picking up the fresh water

***Wastes Disposal Location:***

***Agencies Involved:***

***Updates***

---

***Date:*** 11/25/2015   ***Status:*** Reviewed - Assigned to Other Agency

***Author:*** Souder, Taylor

***Updated Oil Volume:***

***Updated Salt Water Volume:***

***Updated Other Volume:***

***Updated Other Contaminant***

***Notes:***

Release remained on location according to the report. NDIC retains oversight.